

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767
FACSIMILE: (202) 418-1410
E-MAIL: charles.miller@fcc.gov

November 3, 2006

Peter Gutmann, Esq.
Womble Carlyle Sandridge & Rice
1401 I Street NW, Seventh Floor
Washington, DC 20005

Re: WWPR(AM), Bradenton, Florida
Facility Identification Number: 60587
Greenrose Broadcasting Services, Inc.
Special Temporary Authorization

Dear Counsel:

This is in reference to the request filed September 16, 2005¹, on behalf of Greenrose Broadcasting Services, Inc. ("GBS"), requesting extension of the special temporary authority ("STA") granted on March 16, 2005, to operate Station WWPR with the facilities authorized by Construction Permit BP-20040107AAY. In support of the request, GBS states that, following a delay in obtaining necessary field strength measurements, it has filed an application for modification of its permit.

Our review indicates that Construction Permit BMP-20050916ACB was granted on December 19, 2005; however, an application for license to cover the permit has not yet been filed. Thus, a brief extension STA will be granted to allow time for preparation and filing of an application for license.

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station WWPR may continue to operate with the facilities authorized by Construction Permit BMP-20050916ACB; operating power may be reduced but shall not exceed 0.8 kilowatts. It will be necessary to further reduce power or cease operation if complaints of interference are received. GBS must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310.

This authority expires on **February 3, 2007**.

Sincerely,



Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: Greenrose Broadcasting Services, Inc.

¹ Processing of the request was delayed by an OMD "red light" on the applicant's FRN.