

Dale Bickel

From: O'Connor, Mary <moconnor@wbklaw.com>
Sent: Friday, October 26, 2018 1:08 PM
To: Dale Bickel
Subject: RE: Question

Dale,

Sorry this got pushed down on my list, here is what I know for the STA for KLWV (BSTA-20180926AAE).

KLWV is still on at low power, but they've installed an emergency (temporary) antenna. It is an ERI SHPX-1AE mounted at the normal COR of 213 feet.

The TPO is at what it normally would be, but, the ERP is approximately 12kW or about 12% of licensed power.

From: Dale Bickel [mailto:Dale.Bickel@fcc.gov]
Sent: Monday, October 22, 2018 10:03 AM
To: O'Connor, Mary
Subject: RE: Question

I don't see that a new STA is required here, but it would be helpful to have the changes summarized, that we can include with the STA record in CDBS. An e-mail to me would suffice. Dale

From: O'Connor, Mary <moconnor@wbklaw.com>
Sent: Friday, October 19, 2018 1:35 PM
To: Dale Bickel <Dale.Bickel@fcc.gov>
Subject: Question

Dale,

I have a quick question for you. We have and STA that was granted to operate at reduced power, it continue to operate at reduced power, but they've installed an emergency (temporary) antenna at the same COR. Do I need to amend the STA to reflect this change?

Thank you for any insight!

Best,

WILKINSON) BARKER) KNAUER) LLP

MARY N. O'CONNOR
PARTNER
1800 M STREET, NW
SUITE 800N
WASHINGTON, DC 20036
MAIN 202.783.4141
DIRECT 202.383.3351
FAX 202.783.5851

This electronic message transmission contains information from the law firm of Wilkinson Barker Knauer, LLP which may be confidential or privileged. The information is intended to be for the use of the individual or entity named above. If you are not the intended recipient, be aware that any disclosure, copying, distribution, or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at 202.783.4141 or by electronic mail administrator@wbklaw.com immediately.