FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU

AUDIO DIVISION

ENGINEER: CHARLES N. (NORM) MILLER

TELEPHONE: (202) 418-2767

TELEPHONE: (202) 418-2767 FACSIMILE: (202) 418-1410 E-MAIL: charles.miller@fcc.gov

HOME PAGE: www.fcc.gov/mb/audio/

APPLICATION STATUS: (202) 418-2730

October 7, 2008

Mark N. Lipp, Esq. Wiley Rein LLP 1776 K Street NW Washington, DC 20006

Re: CMP KC Licensing, LLC

KFNC(FM), Beaumont, Texas

Facility Identification Number: 52407

Special Temporary Authority

Dear Counsel:

This is in reference to the request filed October 3, 2008, on behalf of CMP KC Licensing, LLC ("CKL"). CKL requests special temporary authority ("STA") to operate Station KFNC with temporary facilities.¹ In support of the request, CKL states that the station's licensed antenna system was destroyed by Hurricane Ike. CKL requests STA for operation from the licensed auxiliary antenna of Station KHJK pending restoration of the licensed KFNC tower and antenna.

Section 73.1680 of the Commission's rules provides for operation with emergency antenna facilities following damage to authorized antenna systems, provided that an informal request for continued use of an emergency antenna is filed with the Commission within 24 hours. In particular, Section 73.1680(b)(2) provides that FM and TV stations may erect any suitable radiator, or use operable sections of the authorized antenna(s) as an emergency antenna.

Accordingly, the request for STA IS HEREBY GRANTED. Station KFNC may operate with the following facilities:

Geographic coordinates: 29° 56′ 09″ N, 94° 30′ 39″ W (NAD 1927)

Channel 248 (97.5 MHz)

Effective radiated power: Not to exceed 8 kilowatts (H&V)

Antenna height:

above ground: 552 meters above mean sea level: 564 meters Above average terrain: 555 meters

Simultaneous operation of Stations KHJK and KFNC with the foregoing antenna is not

¹ KFNC is licensed for operation on Channel 248C (97.5 MHz) with effective radiated power of 100 kilowatts (H&V) and antenna height above average terrain of 596 meters.

authorized. CKL must notify the Commission when licensed operation is restored. CKL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on April 7, 2009.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,

Charles N. Miller, Engineer

Audio Division Media Bureau

cc: CMP KC Licensing, LLC