

FEDERAL COMMUNICATIONS COMMISSION

**445 12th STREET SW
WASHINGTON DC 20554**

**MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio**

**PROCESSING ENGINEER: Arthur E. Doak
TELEPHONE: (202) 418-2715
FACSIMILE: (202) 418-1410
MAIL STOP: 1800B3-AED
INTERNET ADDRESS: arthur.doak@fcc.gov**

August 24, 2009

Dayspring Ministries of Concord Baptist Church
136 Wando Circle
Lexington, SC 29073

In re: New(FM), Dodge City, KS
Dayspring Ministries of Concord Baptist Church
Facility ID No.: 176783
BNPED-20071022AFA

Dear Applicant:

This letter is in reference to the above-captioned application for a new non-commercial educational FM station to serve Dodge City, Kansas on Channel 206C1. The application was last amended on July 24, 2008.

Our study has revealed discrepancies in the antenna site coordinates and the tower height above ground level (AGL). The North American Datum 27 (NAD 27) coordinates listed in Section VII, Item 3 of the application are 37° 39' 1" NL, 100° 40' 9" WL. Furthermore, the tower height AGL listed in Section VII, Item 6 of the application is 244 meters. However, the North American Datum 83 (NAD 83) coordinates listed in the tower registration record (Antenna Structure Registration No. 1033277 are 37° 39' 1" NL, 100° 40' 8" WL. These coordinates, when converted to NAD 27, are 37° 39' 1" NL, 100° 40' 6" WL. Furthermore, in the tower registration record the tower height AGL is 269 meters. These discrepancies must be resolved before processing of the application can continue.¹ If the tower registration is correct, all pertinent sections and exhibits of the application must be amended. However, if the application is correct, the tower registration record must be corrected.

Further action on the subject application will be withheld for a period of twenty (20) days from the date of this letter to provide you an opportunity to submit an amendment correcting these discrepancies. Failure to file an amendment within this time period which corrects the discrepancies will result in the dismissal of the application for failure to prosecute pursuant to 47 C.F.R. § 73.3568(a)(1).

Sincerely,

Arthur E. Doak

Arthur E. Doak
Senior Engineer
Audio Division
Media Bureau

cc: Mr. Joseph A. Wells III

¹ Please note, any change in the coordinates or the tower height AGL could affect the antenna heights and tower height figures listed in Section VII, Items 7, 8 and 9.