## FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU AUDIO DIVISION

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER TELEPHONE: (202) 418-2767

FACSIMILE: (202) 418-1410 E-MAIL: charles.miller@fcc.gov

April 14, 2010

Carrie A. Ward, Esq. Entercom Communications Corp. 401 City Avenue, Suite 809 Bala Cynwyd, Pennsylvania 19004

Re: WEEI(AM), Boston, Massachusetts

Facility Identification Number: 1912 Entercom Boston License, LLC Special Temporary Authorization

## Dear Counsel:

This is in reference to the request filed April 12, 2010, on behalf of Entercom Boston License, LLC ("Entercom"). Entercom requests special temporary authority ("STA") to operate Station WEEI during nighttime hours with parameters at variance from licensed values and/or reduced power while maintaining monitor points within licensed limits, except that authority is requested for operation with the 260° monitor point not to exceed 15 mV/m.¹ Entercom states that the existing 260° monitor point is no longer representative of the radial, and submits an engineering showing that the requested operation will not result in radiation in excess of the licensed directional pattern. Entercom further states that it plans to file an application to augment its licensed nighttime pattern.

Accordingly, the request for STA IS HEREBY GRANTED. Station WEEI may operate during nighttime hours with parameters at variance from licensed values and/or reduced power while maintaining monitor points within licensed limits, except that the field strength at the 260° monitor point shall not exceed 15 mV/m. It will be necessary to further reduce power or cease operation if complaints of interference are received. It is anticipated that an application for construction permit to augment the nighttime pattern will be filed prior to the expiration date below. Entercom must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on October 14, 2010.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under

<sup>&</sup>lt;sup>1</sup> WEEI is licensed for operation on 850 kHz with 50 kilowatts, unlimited hours, employing different directional antenna patterns daytime and nighttime (DA-2-U).

temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.

Accordingly, Special Temporary Authorities by nature are to be temporary and are not intended for extended use. Licensees of stations operating under temporary authorities are reminded that timely restoration of permanent facilities is the responsibility of the licensee and should be undertaken expeditiously. Any request for extension of special temporary authorities carries an increased burden with each subsequent request.

Therefore, requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Sincerely,

Charles N. Miller, Engineer

Audio Division Media Bureau

cc: Entercom Boston License, LLC