

**FEDERAL COMMUNICATIONS COMMISSION**  
**445 12<sup>th</sup> STREET SW**  
**WASHINGTON DC 20554**

**MEDIA BUREAU**  
**AUDIO DIVISION**  
**APPLICATION STATUS:** (202) 418-2730  
**HOME PAGE:** [www.fcc.gov/mb/audio/](http://www.fcc.gov/mb/audio/)

**PROCESSING ENGINEER:** Edward Lubetzky  
**TELEPHONE:** (202) 418-2700  
**FACSIMILE:** (202) 418-1410/11  
**MAIL STOP:** 1800B2-EAL  
**INTERNET ADDRESS:** [Edward.Lubetzky@fcc.gov](mailto:Edward.Lubetzky@fcc.gov)

October 22, 2010

Dennis J. Kelly, Esq.  
Post Office Box 41177  
Washington, DC 20018

Re: Covenant Network  
KHOJ(AM), St. Charles, MO  
Facility ID Number: 7114  
Construction Permit: BP-20050706ACB  
As modified by BMP-20090903AAW  
License Application: BMML-20100604AGC

Dear Mr. Kelly:

After initial review of the license application, the staff found the following deficiencies:

1. The moment method proof did not include a certificate or statement of calibration verifying that the antenna monitor is properly calibrated according to the manufacturer's specifications, as Section 73.69(e) requires.<sup>1</sup>
2. Reference field strength measurements on the daytime 114° null radial were not provided.

Further action on the subject license application will be withheld until Covenant submits an amendment addressing the deficiencies described above. Failure to respond within 60 days from the date of this letter may result in the dismissal of the application pursuant to 47 C.F.R. § 73.3568(a)(1) of the Commission's rules.

Sincerely,



Ann Gallagher  
Audio Division  
Media Bureau

cc: Mark A. Mueller  
Covenant Network

---

<sup>1</sup> Covenant only states : "The Potomac Instruments AM-19 antenna monitor is operating properly and continues to be used:"