

Marlene H. Dortch, Secretary
Federal Communications Commission
Office of the Secretary
445 12th Street, SW
Washington, DC 20554

RECEIVED

2014 JAN 23 A 7:27

Received & Inspected
JAN 16 2014
FCC Mail Room

January 14, 2014

Re: New-LP Rocky Mount VA
Facility ID Number 196071
Rocky Mount Community Radio
File Number BNPL-20131114AMV

Ms Dortch,

We would like to file a petition for reconsideration for a LPFM for Rocky Mount Va. We applied during the recent filing window and due to issues with you CDBS that were well published apparently our coordinates were accepted incorrect.

Our application was dismissed by Mr James Bradshaw on 12/16/2013. We have spoke with the Engineer Mr Gary Loehrs who performed the engineering study and he stated that only you could make this change.

This was a small typographical error and would like the chance to correct this and our application be reinstated. The coordinates on file are 39-59-41.6 N and 9-54-0.2W they should have read 39-59-41.6N and 79-54-0.2W No other changes are requested.

We believe that the public interest would be well served if this application would be reinstated and the coordinates corrected.

Thank you for your time and consideration

Sincerely



Cynthia Hodges

Rocky Mount Community Radio

JAN 16 2014

FCC Mail Room

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET, SW
WASHINGTON, DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

DEC 16 2013

ENGINEER: GARY A. LOEHRS
TELEPHONE: (202) 418-2700
FACSIMILE: (202) 418-1410/1411
MAIL STOP: 1800B3
INTERNET ADDRESS: Gary.Loehrs@fcc.gov

Rocky Mount Community Radio
65 Luke St.
Rocky Mount, VA 24151

Re: NEW-LP, Rocky Mount, VA
Facility ID No. 196071
Rocky Mount Community Radio
File No. BNPL-20131114AMV


Dear Applicant:

The staff has under consideration the above-captioned application for a new low power FM (LPFM) station.

An engineering study has revealed a deficiency with the transmitter site coordinates proposed in the application. The application indicates the coordinates are 39° 59' 41.6" N. and 9° 54' 0.2" W. (NAD 27). However, these coordinates are located outside the borders of the United States, its territories, its possessions, and the District of Columbia. The coordinates are far enough away from any US land area that a minor amendment would not be able to eliminate this defect. Therefore, we must dismiss the application.

Accordingly, in light of the above, application BNPL-20131114AMV is unacceptable for filing and IS HEREBY DISMISSED. This action is taken pursuant to 47 C.F.R. § 0.283.

Sincerely,



James D. Bradshaw
Deputy Chief
Audio Division
Media Bureau