

Received & Inspected

JAN 21 2015

FCC Mail Room

CALVARY CHAPEL OF TWIN FALLS, Inc.PO Box 391
4002 N. 3300 E.

Twin Falls, ID 83303

Ph(208)734-6633 Ext. 206 – Fax (208)736-1958

loism@csnradio.com

2015 JAN 22 A 9:04

January 15, 2014

Office of the Secretary
Federal Communications Commission
445 12th Street, SW, Washington, DC 20554
Attn: Chief, Audio Division, Media Bureau

ATTENTION: FM Branch, Mass Media Bureau
REFERENCE: BSTA-20141024ACE/Request to Dismiss
STATION: KPIJ Junction City, Facility ID 92491

Dear Audio Services Chief:

Calvary Chapel of Twin Falls, Inc. hereby notifies the Commission that KPIJ Junction City, OR, Facility ID 92491 has resumed normal operations as of 1/14/2015. The power divider has been repair from the factory and replaced at the tower site. Both antennas are now hooked up to the power divider and KPIJ has been restored to normal power.

Calvary Chapel of Twin Falls, Inc. respectfully requests that the Commission please dismiss BSTA-20141024ACE. If you have any questions, please contact me at (208)733-3133 ext. 206. Thank you.

Sincerely,



Lois Mills
Applications Technician
Calvary Chapel of Twin Falls, Inc.

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

Received & Inspected

JAN 21 2015

FCC Mail Room

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
www.fcc.gov/encyclopedia/audio-division-media-bureau

ENGINEER: Dale Bickel
TELEPHONE: (202) 418-2706
FACSIMILE: (202) 418-1410

E-MAIL: dale.bickel@fcc.gov

October 30, 2014

Calvary Chapel of Twin Falls, Inc.
P.O. Box 391
Twin Falls, ID 83303

Re: KPIJ (FM), Junction City, OR
Calvary Chapel of Twin Falls, Inc. ("CCTF")
Facility Identification Number: 92491
Special Temporary Authority
BSTA-20141024ACE

Dear Licensee:

This is in reference to your request filed October 24, 2014. You explain that KPIJ went silent on September 24 following an apparent failure of the station's antenna, that was later traced to the antenna power divider. Until the antenna power divider can be replaced, CCTF requests Special Temporary Authority to operate the southeast directional antenna element at 0.267 kW ERP. CCTF has worked with the antenna manufacturer to verify that operation at this power level will maintain the STA's 60 dBu service contour within the authorized 60 dBu service contour.

The request for STA IS HEREBY GRANTED. Station KPIJ may operate at 0.267 kW ERP using only the southeastern antenna element. CCTF must advise the Commission when licensed operations are restored. CCTF must use whatever means are necessary to protect workers and the public from radiofrequency exposure in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310.

This authority expires on **January 30, 2015**.

STA Advisory: Section 309(f) of the Communications Act of 1934, as amended, authorizes the Commission to grant STA in cases of "extraordinary circumstances requiring temporary authorizations in the public interest and when delay in the institution of the temporary operations would seriously prejudice the public interest." However, Section 309(f) is not a means by which a licensee/permittee may circumvent established processing procedures which require the filing of an application, nor is it a means by which a broadcaster may enhance his facility or make operation more convenient for the broadcaster. Stations operating with less than licensed facilities under temporary authorities can be viewed as receiving the benefit of a larger protection area than that in which they are currently providing service.