FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU AUDIO DIVISION APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/ ENGINEER: Joseph Szczesny TELEPHONE: (202) 418-2700 FACSIMILE: (202) 418-1410 E-MAIL: Joseph.Szczesny@fcc.gov

October 14, 2015

Arthur S. Lui, President Multicultural Radio Broadcasting Licensee, LLC 27 William Street, 11th Floor New York, NY 10005

> Re: Multicultural Radio Broadcasting Licensee, LLC (MRBL) KAHZ(AM), Pomona, CA Facility Identification Number: 61814 Special Temporary Authority BESTA- 20150918AAV

Lui Dear Mr. Lipp:

This is in reference to the request filed on September 18, 2015. MRBL requests an extension of the STA last modified on March 24, 2015, to operate station KAHZ(AM) with reduced power during daytime hours and with emergency antena facilities during nighttime hours due to transmission line and transmitter problems.¹ In support of the request, MRBL states that although the transmitter has been repaired and full power daytime operations resumed, it plans to complete all transmission line repairs and restore licensed nighttime operations in the near future.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Accordingly, the request for extension of STA IS HEREBY GRANTED and station KAHZ(AM) may continue to operate nighttime with an emergency ND antenna and reduced power not to exceed 1.25 kW (with licensed full power daytime operations resumed). It will be necessary to further reduce

¹ KAHZ(AM) is licensed for operation on 1600 kHz with 5 kW (ND day and DA night).

power or cease operation if complaints of interference are received. Multicultural must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310. MRBL must file an FCC Form 302 application if any changes to the licensed operating parameters are needed. Otherwise a one page letter must be filed to the attention of supervisory engineer Son Nguyen to request that the last license (BL-19850228AH) be electronically reissued to certify resumption with the licensed operating parameters, and to make any other necessary updates (since granted 30 years ago).

This authority expires on April 14, 2016.

Sincerely, Joseph Szczesny, Engineer Audio Division

Media Bureau

cc: Mark N. Lipp, Esq., WR LLP (via e-mail)