

## Arthur Doak

---

**From:** Fawcett, William D - fawcetwd <mvbs.inc@gmail.com>  
**Sent:** Thursday, June 21, 2018 1:26 PM  
**To:** Arthur Doak  
**Subject:** Re: WMLU(FM), Farmville, VA  
**Attachments:** WMLU Interference Study.pdf; WMLU 60 dBu contour.pdf

Arthur,

I must have had a problem with some datum conversions.  
The correct coordinates for the specified location are:

37-17-52.0  
78-23-42.1

I ran the Interference study again - no change.

Thank you.

-Bill Fawcett  
Mountain Valley Broadcast Service, Inc.  
Harrisonburg, VA (540) 810-9300

On 6/15/2018 1:17 PM, Arthur Doak wrote:

Mr. Fawcett:

Regarding Application BPED-20180416AAI for WMLU(FM), Farmville, Virginia (Fac ID 4311). There is a discrepancy in the North Latitude coordinates. Section VII, Item 3 of the application lists the North Latitude Seconds as 52.2 and all of the exhibits list it as 52.7. Please let me know which is correct. If you have any questions please call me at (202) 418-2715.

Thank You

Arthur Doak  
Audio Division  
Media Bureau  
FCC  
(202) 418-2715