Arthur Doak

From: Sent: To: Subject: Arthur Doak Tuesday, July 3, 2018 10:19 AM Fawcett, William D - fawcetwd RE: WMLU(FM), Farmville, VA

Mr. Fawcett:

After our phone conversation today, I am still be concerned with someone on the main roof (outside the penthouse) on stepladder or a ladder leaning against the penthouse. Therefore, I still think it is best to have warning signs on the main roof and at the main roof access and limit access even to the main roof.

Thanks

Art Doak Audio Division Media Bureau FCC (202) 418-2715

From: Fawcett, William D - fawcetwd [mailto:mvbs.inc@gmail.com] Sent: Thursday, June 21, 2018 1:26 PM To: Arthur Doak <Arthur.Doak@fcc.gov> Subject: Re: WMLU(FM), Farmville, VA

Arthur,

I must have had a problem with some datum conversions. The correct coordinates for the specified location are:

37-17-52.0 78-23-42.1

I ran the Interference study again - no change.

Thank you.

-Bill Fawcett Mountain Valley Broadcast Service, Inc. Harrisonburg, VA (540) 810-9300

On 6/15/2018 1:17 PM, Arthur Doak wrote:

Mr. Fawcett:

Regarding Application BPED-20180416AAI for WMLU(FM), Farmville, Virginia (Fac ID 4311). There is a discrepancy in the North Latitude coordinates. Section VII, Item 3 of the application lists the North

Latitude Seconds as 52.2 and all of the exhibits list it as 52.7. Please let me know which is correct. If you have any questions please call me at (202) 418-2715.

Thank You

Arthur Doak Audio Division Media Bureau FCC (202) 418-2715