

Insert shipping
document here



ORIGIN ID: NSFA (301) 933-6304
J. NEELY
MILLER AND NEELY, PC
3750 UNIVERSITY BLVD., WEST
SUITE 203
KENSINGTON, MD 20895
UNITED STATES US

SHIP DATE: 20APR21
ACTWGT: 0.25 LB
CAD: 9574062/INET4340

BILL SENDER

TO FEDERAL COMMUNICATIONS COMMISSION
FEDERAL COMMUNICATIONS COMMISSION
9050 JUNCTION DRIVE

ANNAPOLIS JUNCTION MD 20701


(301) 333-5435

REF. CLAYPOOL

INV

PO

DEPT.



FedEx
Express



J21121032101ur

FedEx Ship Manager - Print Your Label(s)

FRI - 23 APR 4:30P
EXPRESS SAVER

TRK# 7734 9237 2806
0201

SE ZFEA

20701
MD-US BWI



Received & Inspected

APR 22 2021

FCC Mailroom



Tracking No: 773492372806

DORTCH, MARLENE
TW-B204F

Phone: 418-1449
Received On: 04-22-2021 12:02pm

4/20/2021

John S Neely*

*admitted in PA and DC only

Law Offices
Miller and Neely, PC
4 Simms Court
Kensington, MD 20895
April 19, 2021

(301) 933-6304

Jerry Miller (of counsel)

Secretary
Federal Communications Commission
Washington, DC 20554

Accepted / Filed

APR 22 2021

Federal Communications Commission
Office of the Secretary

ATTN: Media Bureau (Audio)

RE: KIKO-FM Claypool, AZ
FACID 11894

Dear Madam Secretary:


1TV.COM, Inc., licensee of the above-referenced station advises as follows:

The directional antenna associated with the above-referenced station has sustained falling ice damage to the extent that some antenna elements are now malformed. In consultation with its broadcast engineering consultants, the licensee is advised that from initial observation it would appear that the antenna system is in compliance with permissible operating parameters.

Out of an abundance of caution, the licensee has contacted the antenna manufacturer and the licensee is in the process of ordering replacement parts to repair the malformed antenna element(s).

Please address any questions concerning this matter to the undersigned.

Sincerely,


John S. Neely