

Dale Bickel

From: Dale Bickel
Sent: Tuesday, August 31, 2021 8:54 AM
To: DOXENFORD@WBKLAW.COM
Subject: KNYN BSTA-20210825AAL granted 8/31



Special Temporary Authority For a Radio Broadcast Station

Audio Division, Media Bureau

Date: August 31, 2021
File Number(s): BSTA-20210825AAL (BESTA-20191016AAA)
Call Sign: KNYN (FM)
Facility ID Number: 87470

For the reasons provided in the application request, Special Temporary Authority IS GRANTED for operation of the station above with the parameters specified in the STA BSTA-20051121AUH only. The licensee is responsible for addressing any complaints of interference that may arise.

This STA authority expires **February 27, 2022**.

Keep in mind that any permanent solution is subject to the allotment changes specified in the *Report and Order* in MB Docket 02-290, DA-04-1650, <https://docs.fcc.gov/public/attachments/DA-04-1650A1.pdf> (see paragraphs 4 and 5).

Authorized by: Dale Bickel dale.bickel@fcc.gov
Senior Electronics Engineer

A copy of this e-mail will be posted in the FCC's CDBS database under the file number above. Please retain a copy of this authorization for your records.

Considerations:

Licensee must take all steps to ensure that workers and the public are not exposed to radiofrequency exposure in excess of the Commission's exposure limit.

This Special Temporary Authority does not supersede any non-FCC-regulated requirements applicable to the STA-authorized facility. The licensee remains solely and wholly responsible for maintaining compliance with such requirements.

Requests for extension of STA may be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.