

BROADCAST ENGINEERING CONSULTANTS

Timothy C. Cutforth P.E Director of Engineering

303-937-1900 965 S. IRVING STREET DENVER, CO 80219

KFKA MONITOR POINT COORDINATES

| MP # | RADIAL | COORD NL | WL |
|------|--------|---------------------|----------------------|
| 1 | 73deg | 40deg 22min 27.4sec | 104deg 41min 44.1sec |
| 2 | 105deg | 40deg 21min 16.0sec | 104deg 40min 40.3sec |
| 3 | 138deg | 40deg 20min 36.8sec | 104deg 42min 24.7sec |
| 4 | 241deg | 40deg 22min 37.4sec | 104deg 47min 01.3sec |
| 5 | 285deg | 40deg 22min 34.8sec | 104deg 47min 04.0sec |
| 6 | 328deg | 40deg 23min 29.7sec | 104deg 45min 23.1sec |

KFKA License Operating Parameters

After verifying that the pattern was in standard pattern tolerance before mounting the FM antenna and connecting the feedline through the isocoil at the tower base it was found that when the isocoil was connected to the FM antenna feedline it caused a shift in the displayed operating parameters. We proceeded with the measurements fully expecting to need to do a talkdown of the array to return to the licensed measured operation but found that the actual pattern shape had changed very little based on the radial field measurements. It was then decided to leave the pattern adjustment as was and file for license with the new operating parameters and the showing that the pattern is nicely within the standard pattern as currently adjusted. The new operating parameters based on 100% and 0degrees for the west reference tower the operating parameters are now 0.78 ratio (up slightly from the licensed 0.75ratio) and 0.0 degrees phase (up from the licensed -7.0 degrees) for the East tower.

The computed pattern field changes from before to after were on the order of 5% or less in any radial direction.

KFKA GROUND SYSTEM

The KFKA ground system was not modified in any way and remains as originally installed described as 120 radials 80m in length except where shortened at the common strap between towers.

KFKA TOWER REGISTRATION West tower

| Registration Detail | | | |
|---|---|--|--|
| Reg Number | 1024496 | Status | Constructed |
| File Number | A0287503 | Constructed | 01/01/1948 |
| EMI | No | Dismantled | |
| NEPA | No | | |
| Antenna Structure | | | |
| Structure Type | 2TA1 - Antenna Tower Array - 1st N = # towers 2nd N = | | |
| Location (in NAD83 Coordinates) | | | |
| Lat/Long | 40-21-57.0 N 104-44-00.0 W | Address | TWR 1 - NR 35TH AVE & 49TH ST SW OF TOWN |
| City, State | GREELEY , CO | | |
| Zip | 80620 | County | WELD |
| Center of AM Array | 40-21-56.0 N 104-43-56.0 W | Position of Tower in Array | |
| Heights (meters) | | | |
| Elevation of Site Above Mean Sea Level | | Overall Height Above Ground (AGL) | |
| 1434.0 | | 85.0 | |
| Overall Height Above Mean Sea Level | | Overall Height Above Ground w/o Appurtenances | |
| 1519.0 | | 85.0 | |
| Painting and Lighting Specifications | | | |
| FCC Paragraphs 1, 3, 12, 21 | | | |
| FAA Notification | | | |
| FAA Study | | FAA Issue Date | |
| Owner & Contact Information | | | |
| FRN | 0007305550 | Owner Entity Type | |
| Assignor FRN | 0005607841 | Assignor ID | L00421431 |
| Owner | | | |
| Music Ventures, LLC, d/b/a Broadcast Media, LLC Attention To: Kenneth W. Sasso 6546 N. Academy Boulevard Colorado Springs , CO 80918 | | P: (719)593-9355 F: E: | |
| Contact | | | |
| Koerner , James A Esq 5809 Nicholson Lane, Suite 124 North Bethesda , MD 20852 | | P: (301)468-3336 F: E: bkofcclaw@erols.com | |
| Last Action Status | | | |
| Status | Constructed | Received | 11/04/2002 |
| Purpose | Change Owner | Entered | 11/04/2002 |

| | | | |
|-----------------------------|------------------------------------|--------------------|---------------------|
| Mode | Interactive | | |
| Related Applications | | | |
| 11/04/2002 | A0287503 - Change Owner (OC) | | |
| 12/03/2001 | A0231378 - Change Owner (OC) | | |
| 11/16/2001 | A0222694 - Change Owner (OC) | | |
| Related applications (4) | | | |
| Comments | | | |
| Comments | | | |
| None | | | |
| History | | | |
| Date | Event | | |
| 11/05/2002 | Change of Ownership Letter Sent | | |
| 11/05/2002 | Registration Printed | | |
| 11/04/2002 | Change of Ownership Received | | |
| All History (6) | | | |
| Pleadings | | | |
| Pleading Type | Filer Name | Description | Date Entered |
| None | | | |
| Automated Letters | | | |
| 11/05/2002 | Authorization, Reference 242858 | | |
| 11/05/2002 | Ownership Change, Reference 242986 | | |
| 12/20/2001 | Ownership Change, Reference 182550 | | |
| All letters (4) | | | |

KFKA TOWER REGISTRATION East tower

| Registration Detail | | | |
|---|---|--|--|
| Reg Number | 1024497 | Status | Constructed |
| File Number | A0287505 | Constructed | 01/01/1948 |
| EMI | No | Dismantled | |
| NEPA | No | | |
| Antenna Structure | | | |
| Structure Type | 2TA2 - Antenna Tower Array - 1st N = # towers 2nd N = | | |
| Location (in NAD83 Coordinates) | | | |
| Lat/Long | 40-21-57.0 N 104-43-53.0 W | Address | TWR 2 - NR 35TH AVE & 49TH ST SW OF TOWN |
| City, State | GREELEY , CO | | |
| Zip | 80620 | County | WELD |
| Center of AM Array | 40-21-56.0 N 104-43-56.0 W | Position of Tower in Array | |
| Heights (meters) | | | |
| Elevation of Site Above Mean Sea Level | Overall Height Above Ground (AGL) | | |
| 1434.0 | 85.0 | | |
| Overall Height Above Mean Sea Level | Overall Height Above Ground w/o Appurtenances | | |
| 1519.0 | 85.0 | | |
| Painting and Lighting Specifications | | | |
| FCC Paragraphs 1, 3, 12, 21 | | | |
| FAA Notification | | | |
| FAA Study | | FAA Issue Date | |
| Owner & Contact Information | | | |
| FRN | 0007305550 | Owner Entity Type | |
| Assignor FRN | 0005607841 | Assignor ID | L00421431 |
| Owner | | | |
| Music Ventures, LLC, d/b/a Broadcast Media, LLC Attention To: Kenneth W. Sasso 6547 N. Academy Boulevard Colorado Springs , CO 80918 | | P: (719)593-9355 F: E: | |
| Contact | | | |
| Koerner , James A Esq 5809 Nicholson Lane, Suite 124 North Bethesda , MD 20852 | | P: (301)468-3336 F: E: bkofcclaw@erols.com | |
| Last Action Status | | | |
| Status | Constructed | Received | 11/04/2002 |
| Purpose | Change Owner | Entered | 11/04/2002 |
| Mode | Interactive | | |

Related Applications

| | |
|------------|------------------------------|
| 11/04/2002 | A0287505 - Change Owner (OC) |
| 12/03/2001 | A0231376 - Change Owner (OC) |
| 11/16/2001 | A0222697 - Change Owner (OC) |

Related applications (4)

Comments**Comments**

None

History

| Date | Event |
|-------------|---------------------------------|
| 11/05/2002 | Change of Ownership Letter Sent |
| 11/05/2002 | Registration Printed |
| 11/04/2002 | Change of Ownership Received |

All History (6)

Pleadings

| Pleading Type | Filer Name | Description | Date Entered |
|----------------------|-------------------|--------------------|---------------------|
|----------------------|-------------------|--------------------|---------------------|

None

Automated Letters

| | |
|------------|------------------------------------|
| 11/05/2002 | Authorization, Reference 242860 |
| 11/05/2002 | Ownership Change, Reference 242988 |
| 12/20/2001 | Ownership Change, Reference 182549 |

All letters (4)