

**[EXTERNAL]: KDCO AM reduced power operations §73.1560(d) notice**

Eric Scace &lt;eric@broadcastradio.engineering&gt;

Tue 2/8/2022 3:43 PM

To: Jerome Manarchuck &lt;Jerome.Manarchuck@fcc.gov&gt;

[You don't often get email from eric@broadcastradio.engineering. Learn why this is important at <http://aka.ms/LearnAboutSenderIdentification>.]

CAUTION: This email originated from outside of the Federal Communications Commission. Do not click on links or open attachments unless you recognize the sender and trust the content to be safe. If you suspect this is a phishing attempt, please use the 'Report Message' feature in Microsoft Outlook or forward the email to the NSOC.

Hello —

I am the contract engineer for KDCO AM (facility ID 34585).

The main transmitter suffered a power supply failure. At present the station is operating on its backup transmitter, but at a reduced power of 0.750 kW (compared to the licensed power of 1 kW). This is below the limit specified in §73.1560(a)(10).

Damaged parts in the main transmitter have been replaced, but I am awaiting a replacement power supply board from the manufacturer.

As we are approaching the end of the 10-day period allowed for reduced power operations in §73.1560(d), I am required to provide notice to the Audio Division (radio).

At present I don't anticipate exceeding the 30-day limit before an STA would be required.

Unfortunately the FCC website isn't specific as to where to send this notice to the Audio Division. Any advice you could provide would be appreciated.

Regards,

— Eric Scace

+1-617-712-1523