

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767
FACSIMILE: (202) 418-1410
E-MAIL: charles.miller@fcc.gov

July 14, 2010

Donald G. Everist, P.E.
Cohen, Dippell and Everist, P.C.
1300 L Street, N.W., Suite 1100
Washington, D.C. 20005

Re: University of Tulsa
KWGS(FM), Tulsa, Oklahoma
Facility Identification Number: 66586
Special Temporary Authority

Dear Mr. Everist:

This is in reference to the request filed June 15, 2010, on behalf of University of Tulsa ("UT"). UT requests extension of the special temporary authority ("STA") granted on March 17, 2010, to operate Station KWGS with reduced power.¹ In support of the request, UT states that a replacement for the station's damaged antenna has been ordered but not yet received.²

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Our review indicates that the licensee has been prevented from restoring licensed operation due to causes beyond its control and has taken all possible steps to expeditiously resolve the problem. Thus, extension of STA is warranted.

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station KWGS may

¹ KWGS is licensed for operation on Channel 208C1 (89.5 MHz) with effective radiated power of 50 kilowatts (H&V) and antenna height above average terrain of 325 meters.

² Station KWGS shares its antenna with commonly owned Station KWTU; however, UT was able to restore KWTU to full power operation following the damage.

continue to operate with reduced power. UT must notify the Commission when licensed operation is restored. UT must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on **September 14, 2010**.

Sincerely,

A handwritten signature in blue ink, appearing to read "Charles N. Miller", with a long horizontal flourish extending to the right.

Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: University of Tulsa