

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: CHARLES N. (NORM) MILLER
TELEPHONE: (202) 418-2767
FACSIMILE: (202) 418-1410
E-MAIL: charles.miller@fcc.gov

June 11, 2012

Troy G. Langham, FCC Engineering Supervisor
Clear Channel Technical & Capital Management
2625 South Memorial Drive, Suite A
Tulsa, Oklahoma 74129

Re: CC Licenses, LLC
WSYR (AM), Syracuse, New York
Facility Identification Number: 48720
Special Temporary Authority

Dear Mr. Langham:

This is in reference to the request filed June 7, 2012, on behalf of CC Licenses, LLC ("CCL"). CCL requests further extension of the special temporary authority ("STA") granted on June 29, 2006, to operate Station WSYR with parameters at variance and/or reduced power while maintaining monitor points within licensed limits, and with a nondirectional antenna and reduced power.¹ In support of the request, CCL states that repair work has been delayed by the unavailability of qualified engineering personnel.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Our review indicates that the licensee has been prevented from restoring licensed operation due to causes beyond its control; thus, extension of STA is warranted.

Accordingly, the request for extension of STA IS HEREBY GRANTED. Station WSYR may

¹ WSYR is licensed for operation on 570 kHz with 5 kilowatts daytime and 5 kilowatts nighttime, employing different directional antenna patterns daytime and nighttime (DA-2-U).

continue to operate with parameters at variance and/or reduced power while maintaining monitor points within licensed limits. Operation with a nondirectional antenna and reduced power not to exceed 1.25 kilowatts also is authorized, only as necessary to facilitate the repair work. It will be necessary to further reduce power or cease operation if complaints of interference are received. CCL must notify the Commission when licensed operation is restored.² CCL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. *See* 47 CFR § 1.1310.

This authority expires on **December 11, 2012**.

Sincerely,



Charles N. Miller, Engineer
Audio Division
Media Bureau

cc: CC Licenses, LLC

² *See* 47 CFR §§ 73.45(c), 73.51, 73.54, 73.61(b).