FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418

APPLICATION STATUS: (202) 418-2730 HOME PAGE: www.fcc.gov/mb/audio/

ENGINEER: Ann Gallagher TELEPHONE: (202) 418-2716 FACSIMILE: (202) 418-1410 E-MAIL: Ann.Gallagher@fcc.gov

January 26, 2012

Mark N. Lipp Wiley Rein LLP 1776 K Street NW Washington, DC 20006

Re: KYPA(AM), Los Angeles, CA

Multicultural Radio

Broadcasting Licensee, LLC

Facility Identification Number: 18273

License application: BMML-20111209KKR

Dear Counsel:

Our review of the subject license application shows the following deficiencies.

- 1. Section 73.151(c)(1) requires a matrix of impedance measurements at the base of each element in the array, with other elements either short- or open-circuited at their respective bases. As the engineering exhibit notes, there are six towers at the site, two of which are used for KYPA. The impedance measurements were taken with the unused elements detuned instead of short- or open-circuited, as the rule requires.
- 2. The measurements made to determine the characteristic impedance of the sampling lines were not done as specified in the rules. Section 73.151(c)(2)(i) states that characteristic impedance shall be determined using open-circuit measurements "at frequencies corresponding to odd multiples of 1/8 wavelength immediately above and below the open circuit resonant frequency closest to carrier frequency."
- 3. The circuit calculations shown in Table 9A, performed to relate current magnitude and phase at the tower base, as computed by the moment method software, to the corresponding readings at the sampling location, appear to show an incorrect phase shift.
- 4. As the Media Bureau's October 29, 2009, *Public Notice*¹ stated, the moment method proof should include a certificate or statement verifying that the antenna monitor is properly calibrated, as Section 73.69(3) requires.

¹ "Media Bureau Clarifies Procedures for AM Directional Antenna Performance Verification Using Moment Method Modeling," Public Notice, DA 09-2340 (2009).

Further action on the subject license application and on the request for program test authority will be withheld until an amendment addressing the deficiencies described above is submitted. Failure to respond within 60 days from the date of this letter may result in dismissal of the application pursuant to 47 CFR Section 73.3568(a)(1).

Sincerely,

Ann Gallagher Audio Division Media Bureau

Cc: Ted Schober