



Federal Communications Commission  
Washington, D.C. 20554

Mat 8, 2014

DTV America Corporation  
1671 NW 144<sup>th</sup> Terrace, Suite 106  
Sunrise, FL. 33323

1800E3-RLG

In re: Low Power Television Application of:  
DTV America Corporation  
Channel 34, Hot Springs, AR.  
File no.: BPDTL-20140130AFJ  
Facility Id No.: 188821

Dear Applicant:

The above referenced application is hereby dismissed.

On February 24, 2014, the licensee was sent a deficiency letter as outlined below:

Specifically, the tower determine results show that the tower heights as specified in the above proposed construction permit fail slope, and require registration with the FAA, to runways at the airport shown in the imported determination results below:

<b>DETERMINATION Results</b>							
<b>FAIL SLOPE (100:1)FAA REQ - 793.0 Meters(2601.67 Feet) away &amp; exceeds by 32.0 Meters (104.989 Feet)</b>							
Type	C/R	Latitude	Longitude	Name	Address	Lowest Elevation (m)	Runway Length (m)
AIRP	R	34-28-23.00N	093-06-23.00W	MEMORIAL FIELD	GARLAND HOT SPRINGS, AR	152.9	2010.2
<b>FAIL SLOPE (100:1)FAA REQ - 988.0 Meters(3241.42 Feet) away &amp; exceeds by 30.0 Meters (98.4200 Feet)</b>							
Type	C/R	Latitude	Longitude	Name	Address	Lowest Elevation (m)	Runway Length (m)
AIRP	R	34-28-53.00N	093-05-57.00W	MEMORIAL FIELD	GARLAND HOT SPRINGS, AR	152.9	2010.2

## Your Specifications

### NAD83 Coordinates

Latitude	34-29-20.7 north
Longitude	093-05-37.5 west

### Measurements (Meters)

Overall Structure Height (AGL)	15.2
Support Structure Height (AGL)	0
Site Elevation (AMSL)	178

You were given the opportunity to file an amendment to resolve the deficiency within 60 days from the date of that letter. Amendments must be filed electronically. Failure to amend your application will result in the dismissal of the application.

Our records show that no amendment has been filed as of May 6, 2014, to resolve the above reference deficiency.

Sincerely

Hossein Hashemzadeh  
Deputy Chief  
Video Division  
Media Bureau