

**FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554**

**MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
HOME PAGE: www.fcc.gov/mb/audio/**

**ENGINEER: JOSEPH SZCZESNY
TELEPHONE: (202) 418-2700
FACSIMILE: (202) 418-1410
E-MAIL: Joseph.Szczesny@fcc.gov**

April 15, 2015

John W. Dickey, Executive VP
Radio License Holding CBC, LLC
3280 Peachtree Road, NW, Suite 2300
Atlanta, GA 30305

Re: Radio License Holding CBC, LLC (RLHC)
WKY (AM), Oklahoma City, Oklahoma
Facility Identification Number: 23418
Special Temporary Authority (STA)
BESTA-20150317ABN

Dear Mr. Dickey:

This is in reference to the request filed on August 25, 2014. RLHC requests a seventh extension of the STA granted on January 25, 2011, to operate with an emergency ND antenna and reduced power due to extensive repairs needed to resume licensed operations.¹ In support of the request, RLHC states that additional time is requested to allow for final action on the AM Revitalization proceeding (MB Docket 13-249).

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.


Accordingly, the request for extension of STA IS HEREBY GRANTED. Station WKY may continue to operate with an emergency ND antenna using the 94.6° night tower #2(SW),

¹ WKY is licensed for operation on 930 kHz with a 5 kW day (ND) and night (DA).

and reduced power not to exceed 5 kW daytime and 1.25 kW nighttime, as necessary to facilitate all repairs. Operation also is authorized during nighttime hours with parameters at variance and/or reduced power while maintaining monitor points within licensed limits. It will be necessary to further reduce power or cease operation if complaints of interference are received. RLHC must file an FCC Form 301 application to modify the facility when the MB Docket 13-249 has been adopted, otherwise all repairs must be completed and the Commission notified when licensed operation has been restored.² RLHC must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310.

This authority expires on **October 15, 2015**.

Sincerely,



Joseph Szczesny, Engineer
Audio Division
Media Bureau

cc: Mark N. Lipp, Esq., Wiley Rein LLP (via e-mail)

² See 47 CFR §§ 73.45(c), 73.51, 73.61(b).