

FEDERAL COMMUNICATIONS COMMISSION
445 TWELFTH STREET SW
WASHINGTON DC 20554

MEDIA BUREAU
AUDIO DIVISION
APPLICATION STATUS: (202) 418-2730
WWW.FCC.GOV/media/radio/audio-division

ENGINEER: Dale Bickel
TELEPHONE: (202) 418-2706
FACSIMILE: (202) 418-1410
E-MAIL: dale.bickel@fcc.gov

October 17, 2016

Unified Pentecostal Local Churches, Inc.
ATTN: Ishmael Lopez
907 N. Pearl, Suite 2
Paola, KS 66071

Re: KWJP (FM), Paola, KS
Unified Pentecostal Local Churches, Inc.
Facility Identification Number: 171650
Special Temporary Authority
BSTA-20161013AAF

Dear Licensee:

This is in reference to the request filed on October 13, 2016, on behalf of Unified Pentecostal Local Churches, Inc. ("UPLC"). UPLC explains that KWJP is currently operating at reduced power due to transmitter damage caused by lightning. UPLC requests Special Temporary Authority (STA) for continued reduced power operation until repairs are completed.

Section 73.1560(d), which governs reduced power operation, states:

In the event it becomes technically impossible to operate at authorized power, a broadcast station may operate at reduced power for a period of not more than 30 days without specific authority from the FCC. If operation at reduced power will exceed 10 consecutive days, notification must be made to the FCC in Washington, DC, Attention: Audio Division (radio) or Video Division (television), Media Bureau, not later than the 10th day of the lower power operation. In the event that normal power is restored within the 30 day period, the licensee must notify the FCC of the date that normal operation was restored. If causes beyond the control of the licensee prevent restoration of the authorized power within 30 days, a request for Special Temporary Authority (see Section 73.1635) must be made to the FCC in Washington, DC for additional time as may be necessary.

Our review indicates that the request complies with Section 73.1560(d).

Accordingly, the request for STA IS HEREBY GRANTED. Station KWJP may continue to operate at reduced power, as needed. UPLC must notify the Commission when licensed operation is restored. UPLC must use whatever means are necessary to protect workers and the public from radiofrequency exposure in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310.

This authority expires on April 15, 2017.

Sincerely,

A handwritten signature in black ink that reads "Dale Bickel". The signature is written in a cursive style with a large initial "D" and a long, sweeping underline.

Dale Bickel
Senior Engineer
Audio Division
Media Bureau

cc: John S. Neely (via e-mail only)