

Dale Bickel

From: Dale Bickel
Sent: Friday, October 13, 2017 9:43 AM
To: Frank Jazzo
Subject: RE: KUOR-FM, Redlands, CA STA Operations

Frank,

As you indicated, the new parameters are very close to the old parameters, and I don't see that a new STA is needed here. However, I'll keep this e-mail to explain the differences, and adjust the STA parameters in the database to match the new parameters.

Dale Bickel dale.bickel@fcc.gov

From: Frank Jazzo [mailto:jazzo@fhhlaw.com]
Sent: Thursday, October 12, 2017 3:29 PM
To: Dale Bickel <Dale.Bickel@fcc.gov>
Subject: KUOR-FM, Redlands, CA STA Operations

Dale,

As we discussed, KUOR-FM is currently operating pursuant to STA, while repairs are made to its licensed facilities. Below are the proposed new STA parameters, the current STA parameters and the licensed parameters. Please let me know if you need anything more in connection with the new STA operations.

Here are the details of the new temporary wooden pole.

The specs in NAD27 for the new pole are:

34-11-46.64N 117-02-55.89W

HAAT = 810 m
AMSL = 2408 m
AGL = 8 m

The current STA spec:

34-11-46.53N 117-02-55.79W

HAAT = 813 m
AMSL = 2402 m
AGL = 15 m

License Spec:

34-11-47.00N 117-02-56.00W

HAAT = 848 m
AMSL = 2419 m

AGL = 17 m

Thanks,

Frank

 **Fletcher, Heald & Hildreth***

Frank R. Jazzo, Member

1300 N. 17th Street, Suite 1100 | Arlington, VA 22209

Tel: 703.812.0470 | Fax: 703.812.0486 | Mobile: 202.422.5894

jazzo@fhhlaw.com | www.fhhlaw.com | www.commlawblog.com

* a Professional Limited Liability Company