

Dale Bickel

From: Dale Bickel
Sent: Tuesday, October 2, 2018 10:50 AM
To: KD4VS@COMCAST.NET
Subject: W275AB BSTA-20180926AAB granted 10/2



Special Temporary Authority For a Radio Broadcast Station

Reduced Power Operation

Audio Division, Media Bureau

Date: October 2, 2018
File Number: BSTA-20160928AAB
Call Sign: W275AB (FX)
Facility ID Number: 8554

For the reasons provided in the application request, Special Temporary Authority IS GRANTED for continued operation of the station above at reduced power, as needed. The licensee must notify the Commission when licensed operation resumes. See 47 CFR Section 73.1560(d).

This STA does not authorize any physical changes to the licensed antenna system.

This STA authority expires **March 31, 2019**.

Authorized by: Dale Bickel dale.bickel@fcc.gov
Senior Electronics Engineer

A copy of this e-mail will be posted in the FCC's CDBS database under the file number above. Please retain a copy of this authorization for your records.

Considerations:

Licensee must take all steps to ensure that workers and the public are not exposed to radiofrequency exposure in excess of the Commission's exposure limit.

This Special Temporary Authority does not supersede any non-FCC-regulated requirements applicable to the STA-authorized facility. The licensee remains solely and wholly responsible for maintaining compliance with such requirements.

Requests for extension of STA may be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.

Reduced power STA requests, or extensions thereof, are filed as "Engineering STA", NOT "Legal STA". Incorrect filing results in delays in processing.

