## FEDERAL COMMUNICATIONS COMMISSION 445 TWELFTH STREET SW WASHINGTON DC 20554

MEDIA BUREAU AUDIO DIVISION

**APPLICATION STATUS: (202) 418-2730** 

HOME PAGE: www.fcc.gov/media/radio/audio-division

ENGINEER: Joseph Szczesny TELEPHONE: (202) 418-2700 FACSIMILE: (202) 418-1410 E-MAIL: Joseph.Szczesny@fcc.gov

January 31, 2019

Lenard D. Liberman, President Liberman Broadcasting of Dallas License LLC 1845 Empire Avenue Burbank, CA 91504

Re: Liberman Broadcasting of Dallas License LLC

(LBDL)

KZMP(AM), University Park, TX Facility Identification Number: 63551 Special Temporary Authority (STA)

BESTA-20181219AAX

Dear Mr. Liberman:

This is in reference to the request filed on December 19, 2018. LBDL requests an extension of the STA granted on June 5, 2017, to continue operating with reduced nighttime power using a temporary transmitter to allow time to complete repairs. In support of the request, LBDL states that additional time is needed to restore licensed operations.

Requests for extension of STA will be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond
  the licensee's control, and the licensee has taken all possible steps to expeditiously resolve
  the problem.

Accordingly, the request for extension of the STA IS HEREBY GRANTED, and LBDL may continue to operate with nighttime DA parameters at variance and reduced power while

<sup>&</sup>lt;sup>1</sup> KZMP(AM) is licensed for DA operation on 1540 kHz with 32 kW day and 0.75 kW night, using different patterns.

maintaining monitor points within licensed tolerances (with no change to the daytime licensed operation). LBDL must use whatever means are necessary to protect workers and the public from exposure to radio frequency radiation in excess of the Commission's exposure guidelines. See 47 CFR § 1.1310. LBDL must file an FCC Form 302 application after repairs are completed (if any changes are needed to the operating parameters), or submit an e-mail to my attention to certify the date the station resumed licensed operations per BL-20020809ABT with negligible changes.

This authority expires on July 30, 2019.

Sincerely,

Jøseph Szczesny, Engineer

Audio Division Media Bureau

cc: Kathleen A. Kirby, Esq., WR LLP (via email only)