Dale Bickel

From: Sent: To: Cc: Subject: Dale Bickel Tuesday, March 30, 2021 10:26 AM chris@kwxx.com James Bradshaw; Albert Shuldiner KAOY / KWXX-FM / KNWB / KMWB STA extensions granted 3/30/2021



Extension of Special Temporary Authority For a Radio Broadcast Station

Audio Division, Media Bureau

Date: March 31, 2021

| File Numbers, | 3/25 Extension request for BSTA-20200325AFR KAOY (FM) 70377 |
|-----------------|--|
| Call Signs, | 3/25 Extension request for BSTA-20200325AFU KWXX-FM 48679 |
| and Facility ID | 3/25 Extension request for BSTA-20200325AFS KNWB (FM) 69054 |
| | 3/25 Extension request for BSTA-20200325AFT KMWB (FM) 164099 |

A four month extension of the Special Temporary Authority listed above, to operate at reduced power, IS GRANTED, subject to all the terms and conditions specified in the original STA authorization.

This extended authority expires August 1, 2021.

Authorized by: Dale Bickel <u>dale.bickel@fcc.gov</u> Senior Electronics Engineer

A copy of this e-mail will be posted in the FCC's CDBS database under the file number above. Please retain a copy of this authorization for your records.

Considerations:

Licensee must take all steps to ensure that workers and the public are not exposed to radiofrequency exposure In excess of the Commission's exposure limit.

This Special Temporary Authority does not supersede any non-FCC-regulated requirements applicable to the STA-authorized facility. The licensee remains solely and wholly responsible for maintaining compliance with such requirements.

Requests for extension of STA may be granted only where the licensee can show that one or more of the following criteria have been met:

- Restoration of licensed facilities is complete and testing is underway;
- Substantial progress has been made during the most recent STA period toward restoration of licensed operation; or
- No progress has been made during the most recent STA period for reasons clearly beyond the licensee's control, and the licensee has taken all possible steps to expeditiously resolve the problem.