

Received & Inspected

RECEIVED

**CALVARY CHAPEL OF TWIN FALLS, Inc.**

SEP 10 2014

2014 SEP 11 A 5:41

PO Box 391

4002 N. 3300 E.

Twin Falls, ID 83303

Ph(208)734-6633 Ext. 206 – Fax (208)736-1958

loism@csnradio.com

FCC Mail Room

September 5, 2014

Office of the Secretary  
Attn: Chief, Audio Division, Media Bureau  
Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Washington, DC 20554

**ATTENTION: FM Branch, Mass Media Bureau**  
**REFERENCE: KPIJ Junction City, Oregon**  
**Facility ID No: 92491 / 10 day Notification**

Dear Staff:

Calvary Chapel of Twin Falls, Inc.(CCTF) respectfully notifies the Commission that KPIJ Junction City, Oregon Facility ID 92491 has been operating at reduced ERP fluctuating between 58 and 64 watts TPO since August 26th. A site visit has been scheduled to determine if the power divider has failed on the antenna system. If normal operations have not resumed within the specified 30 days an STA request, to operate at reduced power, will be electronically filed.

Sincerely,



Lois Mills  
Applications Technician  
Calvary Chapel of Twin Falls, Inc.