

Received & Inspected

MAY 24 2016

FCC Mailroom

CALVARY CHAPEL OF TWIN FALLS, Inc.

PO Box 391

4002 N. 3300 E.

Twin Falls, ID 83303

Ph(208)734-6633 Ext. 206 – Fax (208)736-1958

loism@csnradio.com

2016 MAY 25 A 10:31

Added to 10:31 AM 5/25/16

May 18, 2016

Office of the Secretary

Attn: Chief, Audio Division, Media Bureau

Federal Communications Commission

445 12th Street, SW

Washington, DC 20554

ATTENTION: FM Branch, Mass Media Bureau
REFERENCE: Notification that KIMW, Heflin
BLED- 20160419AAQ Facility ID No: 191575
Back to Normal Operations

Dear Staff:

Calvary Chapel of Twin Falls, Inc.(CCTF) respectfully notifies the Commission that KIMW Heflin LA, Facility ID 191575, which had been operating at reduced power since May 5, 2016 due to a short in the electric panel meter, resumed to normal operations on May 17, 2016 when the electric panel was fixed and the transmitter was again able to make full power.

Sincerely,



Lois Mills

Applications Technician

Calvary Chapel of Twin Falls, Inc.

CALVARY CHAPEL OF TWIN FALLS, Inc.

PO Box 391
4002 N. 3300 E.
Twin Falls, ID 83303
Ph(208)734-6633 Ext. 206 – Fax (208)736-1958
loism@csnradio.com

Received & Inspected
MAY 16 2016
FCC Mailroom

May 12, 2016

Office of the Secretary
Attn: Chief, Audio Division, Media Bureau
Federal Communications Commission
445 12th Street, SW
Washington, DC 20554

ATTENTION: FM Branch, Mass Media Bureau
REFERENCE: Notification that KIMW, Heflin
BLED- 20160419AAQ
Facility ID No: 191575 / 10 day Notification

RECEIVED
2016 MAY 17 A 10:49
AUDIO DIVISION

Dear Staff:

Calvary Chapel of Twin Falls, Inc.(CCTF) respectfully notifies the Commission that KIMW Heflin LA, Facility ID 191575, has been operating at reduced power since May 5, 2016 due to a short in the panel of the newly installed electric meter. CCTF's contract engineer has contacted the electric company that installed the meter and has ordered the parts needed for repairs. When the electric company is able to coordinate a visit to the site with CCTF's contract engineer, the problem should be solved. If normal operations have not resumed within the specified 30 days, an STA request to remain operating at reduced power, will be electronically filed with the Commission.

Sincerely,



Lois Mills
Applications Technician
Calvary Chapel of Twin Falls, Inc.