

Received & Inspected

**CALVARY CHAPEL OF TWIN FALLS, Inc.**

PO Box 391

4002 N. 3300 E.

Twin Falls, ID 83303

Ph(208)734-6633 Ext. 206 – Fax (208)736-1958

loism@csnradio.com

MAR 24 2017

FCC Mail Room

2017 MAR 27 A 10:50

March 20, 2017

Office of the Secretary  
Attn: Chief, Audio Division, Media Bureau  
Federal Communications Commission  
445 12<sup>th</sup> Street, SW  
Washington, DC 20554

**ATTENTION: FM Branch, Mass Media Bureau**  
**REFERENCE: Notification that KIMW, Heflin**  
**BLED- 20160419AAQ**  
**Facility ID No: 191575 / 10 day Notification**

Dear Staff:

Calvary Chapel of Twin Falls, Inc.(CCTF) respectfully notifies the Commission that KIMW Heflin LA, Facility ID 191575, had been operating at 50% power from 3/14/17 to 3/16/17 when the transmitter shut down. When CCTF's contract engineer visited the site later on 3/16/17 he found the main 150 amp breaker inside the building had tripped. When it was reset the rotary phase converter caught on fire. The engineer had a 500 watt transmitter with him and installed it at 500 watts ERP, to put KIMW back on the air. If normal operations have not resumed within the specified 30 days, an STA request to remain operating at reduced power, will be electronically filed with the Commission.

Sincerely,



Lois Mills  
Applications Technician  
Calvary Chapel of Twin Falls, Inc.